



HAYLE HARBOUR AUTHORITY
OPERATIONS LIMITED

LOCAL NOTICES TO MARINERS 8/21

North Cardinal Buoy

- 1** There has been a requirement to reposition the north cardinal buoy which was being damaged by the shore break at low water
- 2** Please note the new position is N50° 12` 17” W005° 26` 12”

Peter Haddock CMIOSH
Harbour Master
Hayle Harbour Authority Operations Ltd